



Republic of the Philippines
LEYTE METROPOLITAN WATER DISTRICT
 A DOH ACCREDITED WATER TESTING LABORATORY

Accreditation No.: 13-001-08-LW-2
 Rapid Filtration Plant, Brgy. Hibunawon, Jaro, Leyte
 Telefax No. (053) 332-7465/332-7424

BACTERIOLOGICAL TEST RESULT FOR WATER

Name of Client: **Catbalogan Water District**
 Address: **Pier 2, Allen Ave., Catbalogan Samar**

Submitted by: **Zaldy Mahinay**
 Contact No.:

Lab. No.	Sample Source and Address	Date and Time of:			Result of Analysis			Remarks
		Collection	Receipt	Examination	Total (MPN)	Fecal (MPN)	HPC (CFU/ML)	
14-524	Faucet, Brgy 09 (CWD) Catbalogan, Samar	6:10 AM	June 20, 2014 3:55 PM	4:55 PM	<1.1	<1.1	19	PASSED
14-525	Faucet, Brgy Guinsorongan(CWD) Catbalogan, Samar	6:22 AM	3:55 PM	5:00 PM	<1.1	<1.1	37	PASSED
14-526	Faucet, Buno-anan (CWD) Catbalogan, Samar	6:33 AM	3:55 PM	5:05 PM	<1.1	<1.1	48	PASSED
14-527	Faucet, Brgy 6 (CWD) Catbalogan, Samar	6:46 AM	3:55 PM	5:10 PM	<1.1	<1.1	25	PASSED

2. This result shall not be reproduced unless in full.

Philippine National Standards for Drinking Water (PNSDW)
 MPN = Most Probable Number
 CFU = Colony Forming Unit

Refilling Station
 Less than 1.1 or 0
 Less than 1.1 or 0
 Less than 500 CFU/ml

Public Water Supplies
 Less than 1.1 or 0
 Less than 1.1 or 0
 Less than 500 CFU/ml

Analyst: *Rubyn*

KATHERINE S. ZABALA, RMT
 Medical Technologist

Certified Correct:

Rosalinda A. Dumagsa
ROSALINDA A. DUMAGSA
 Quality Control/Assurance Officer

Noted:

Cynthia L. Terrado

CYNTHIA L. TERRADO
 OIC, Div. Mgr., Quality Control

Encoded by: *airlitamacopibabaino*